

EV-CIS Software Release Notes, Release 37.0				
Кеу	Manufacturer Software Release Notes	Compliance Program		
Light-Duty				
Light-Duty MCT Calculations (Phase 3)				
EVCIS-18920, EVCIS-18928, EVCIS-18979	New Feature/Functionality: The Light-Duty CAFE/GHG module is updated to include MCT calculations (Phase 3)	Light-Duty		
	Description: Manufacturers will see that calculations are performed for MCT submissions and are validated to ensure conformance with the latest requirements.			
L	D California LEV IV Emission Standards & Test Procedure	es		
EVCIS-18893, EVCIS-18993, EVCIS-19234, EVCIS-18991, EVCIS-18992, EVCIS-18896, EVCIS-18988	New Feature/Functionality: Light-Duty vehicle and truck manufacturers will have their submissions validated against California LEV IV testing guidelines and emission standards. Description: Manufacturers will: - See that their Light-Duty vehicle and truck submissions are validated against California LEV IV testing guidelines and emission standards. - See new enumerations so that they may test and certify to California LEV IV testing guidelines and emission standards	Light-Duty		
	Locomotive			
	Locomotive Submission Management Home Page			
EVCIS-18926, EVCIS-18955, EVCIS-18956, EVCIS-18957, EVCIS-19120	New Feature/Functionality: The Locomotive industry Home page has been updated to display the Submission Management Widget.	Locomotive		
	Description: Manufacturers will see the Submission Management Widget on the Locomotive Home page.			
Locomotive Setup Tab				
EVCIS-18969, EVCIS-18912, EVCIS-18945, EVCIS-18946, EVCIS-18973, EVCIS-18982, EVCIS-18983, EVCIS-19050, EVCIS-19052, EVCIS-19126	New Feature/Functionality: The Locomotive industry now directs first to a Setup tab upon creating a new submission. Description: Manufacturers will see the that the Locomotive industry includes a Setup tab and can enter data for the submissions setup on this tab.	Locomotive		

Кеу	Manufacturer Software Release Notes	Compliance Program		
	Locomotive Front-End Business Rules Display			
EVCIS-18959, EVCIS-18971, EVCIS-18972, EVCIS-18980, EVCIS-19105	New Feature/Functionality: If Business Rules are triggered by data entered in a Locomotive industry submission, the rules will appear on screen when a user validates and/or submits the record.	Locomotive		
	Description: Manufacturers will: - See any triggered Locomotive Business Rules on the Review screen of their Locomotive submission upon clicking 'Validate and Submit' and be able to navigate to relevant data elements to remediate any issues.			
	Locomotive Submission Management Infrastructure			
EVCIS-18929, EVCIS-18953, EVCIS-19144, EVCIS-19026, EVCIS-19027, EVCIS-19028, EVCIS-19071, EVCIS-19081, EVCIS-19094	New Feature/Functionality: Locomotive industry services, applications, libraries and general backend infrastructure has been updated to prepare for and handle submission management.	Locomotive		
	Description: Manufacturers will: - See current and previous submissions appear on the Locomotive Home screen in the Submission Management widget and be able to take action on those submissions.			
	Locomotive Submission Management Widget Actions			
EVCIS-18929, EVCIS-18953, EVCIS-19144, EVCIS-19026, EVCIS-19027, EVCIS-19028, EVCIS-19071, EVCIS-19081, EVCIS-19094	New Feature/Functionality: All widget actions that appear on the Locomotive industry home page through the Submission management widget can be used to take different actions on the selected record. Description: Manufacturers will: - Be able to create, edit, revise, delete, and view the record and its history via actions on the Locomotive industry home page through the Submission management widget.	Locomotive		
Locomotive Testing Feedback and Bug Fixes				
EVCIS-18764	Problem: The Certified Engine Family name would not trigger a Red Error Validation when the user entered engine family where 2nd through 4th character was not equal to the manufacturer code. Solution: System will now trigger a Red Error Validation when the user enters an engine family where 2nd through	Locomotive		
	4th character is not equal to the manufacturer code.			
EVCIS-18763	Problem: Missing confirmation modals for actions that clear Test tab form data in General Information have been added. Solution: Added missing confirmation modals for actions	Locomotive		
	that clear Test tab form data in General Information.			

Кеу	Manufacturer Software Release Notes	Compliance Program
EVCIS-18958	New Feature/Functionality: The session timer and timeout	Locomotive
	functionality for the Locomotive industry has been returned	
	to twenty minutes.	
	Description: Manufacturers will see that the session timer	
	and timeout functionality for the Locomotive industry has	
	been returned to twenty minutes.	
EVCIS-19020, EVCIS-19031,	Problem: Several validations and on-screen instructions do	Locomotive
EVCIS-19032, EVCIS-19033	not match the data requirements.	
	Solution: Affected data elements were updated to have their	
	on-screen instructions, information, and validation match	
	data requirements.	
EVCIS-19376	New Feature/Functionality: Manufacturers will be able to	Locomotive
	Revise a submission management record regardless of	
	Dataset Status.	
	Description: Manufacturers will see:	
	- Delete Action appears for records with a Submission Status of "Submitted" regardless of Dataset Status.	
	- Delete Action is hidden for records with certification	
	datasets that have already been deleted.	
	- Revise Action appears for records with a Submission	
	Status of "Submitted" regardless of Dataset Status.	
	- "N = New Submission" option added to Process Code	
	dropdown on Setup tab for revisions.	
	- For Revision Records, the amendment text area will be	
	disabled and cleared if selecting "N = New Submission"	
	Marine Compression Ignition	
	Marine Cl Maintenance and Enhancements	
EVCIS-11076	Problem: Users prevented from submitting a	MCI
	correction/running change when Engine Type (MCI-10)	-
	equals 'RL'.	
	Solution: MCI-BR337 updated to allow users to submit a	
	correction/running change when Engine Type (MCI-10)	
	equals 'RL'.	
	MC-ATV	
	MC-ATV Maintenance and Enhancements	
EVCIS-9804	Problem: Users not allowed to enter '0' for the 'Projected	MC-ATV
	Sales (CBI) - US (49 States)' field except for when the	
	'Sales Area Identifier' field is equal to '49S' (Any State	
	Excluding California).	
	Solution: '0' can now be entered for the 'Projected Sales	
	(CBI) - US (49 States)' field except for when the 'Sales Area	
	Identifier' field is equal to '49S' (Any State Excluding	
	California).	
	, ,	

Кеу	Manufacturer Software Release Notes	Compliance Program		
Nonroad Spark Ignition				
Nonroad Spark Ignition Maintenance and Enhancements				
EVCIS-19048	Problem: Missing Evaporative/Permeation Units cause an exception when creating draft certificate for NRSI evaporative families. Solution: Users will: - See Evaporative/Permeation Units are populated as expected - Be able to create a draft certificate record without exceptions.	NRSI		