



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
REGION 5  
77 WEST JACKSON BOULEVARD  
CHICAGO, IL 60604-3590

REPLY TO ATTENTION OF  
ECW-15J

**VIA ELECTRONIC MAIL**

Mayor Curtis McCall Sr.  
City of Cahokia Heights  
103 Main Street  
Cahokia Heights, Illinois 62206  
ymccall@cahokiaillinois.org

Subject: April 20, 2022, SSO Inspection Trip Report for City of Cahokia Heights

Dear Mayor McCall:

Enclosed, please find a copy of the U.S. Environmental Protection Agency Inspection Trip Report that describes and documents the observation made by the EPA inspection team in the City of Cahokia Heights on April 20, 2022. The purpose of the reconnaissance inspection in the City of Cahokia Heights was to observe locations where sanitary sewer overflows had happened in the past and document their condition under both dry and wet-weather conditions.

If you have any questions or concerns regarding this letter, or the inspection trip report, please contact Dean Maraldo at (312) 353-2098 or at [maraldo.dean@epa.gov](mailto:maraldo.dean@epa.gov).

Sincerely,

Digitally signed by Ryan  
Bahr  
Date: 2022.12.06  
15:10:26 -06'00'

**Ryan Bahr**

Ryan J. Bahr  
Supervisor, Section 2 Water Enforcement and Compliance Assurance Branch

Enclosure

cc: Sharlin Pfeffer, City of Cahokia Heights [spfeffer@cahokiaillinois.org]  
Dennis Traiteur, City of Cahokia Heights [dtraiteur@cahokiaillinois.org]  
Todd Bennett, Illinois EPA [Todd.Bennett@Illinois.gov]  
Joe Stitely, Illinois EPA [Joe.Stitely@Illinois.gov]

**Purpose:** NPDES SSO Inspection Trip Report

**Facility:** Cahokia Heights, Illinois

**NPDES ID Number (No NPDES Permit):** ILN000019

**Date of Inspection:** April 20, 2022

**Illinois EPA Inspectors:** None

**EPA Inspectors:**

Joan Rogers, EPA Region 5; (312) 886-2785; [rogers.joan@epa.gov](mailto:rogers.joan@epa.gov)

Cheryl Burdett, EPA Region 5; (312) 886-1463; [burdett.cheryl@epa.gov](mailto:burdett.cheryl@epa.gov)

**City of Cahokia Heights Representatives:** None

**Inspection Trip Report Prepared by:**

Joan Rogers, EPA Region 5 Inspector

EPA Inspector Signature: JOAN  
ROGERS  Digitally signed by JOAN  
ROGERS  
Date: 2022.12.02  
14:53:38 -06'00'

**Approver Name & Title:**

Ryan Bahr, Supervisor, Compliance Section 2

Approval Signature and Date: Ryan Bahr  Digitally signed by Ryan  
Bahr  
Date: 2022.12.06  
15:10:45 -06'00'

On April 20, 2022, EPA inspectors Joan Rogers, and Cheryl Burdett, conducted a Sanitary Sewer Overflow (SSO) reconnaissance inspection in the City of Cahokia Heights and observed one chronic SSO locations to document whether it was discharging or had evidence of recent discharges. It had not rained in the 24 hours before the observations. The last rainfall recorded at the St. Louis Downtown Airport (KCPS) in St. Clair County was 0.12” on April 18, 2022. This trip report summarizes the inspection observations.

Location #1: Cleanout on North 82<sup>nd</sup> Street

EPA inspectors arrived at the cleanout overflow location on North 82<sup>nd</sup> Street at 2:10 P.M. The cleanout was discharging. EPA inspectors observed the flowing water flow from the ditch next to the street to the ditch along the side yard.



1: P4200252

Description: The cleanout on North 82<sup>nd</sup> Street was overflowing on the day of the inspection.

Location: North 82<sup>nd</sup> Street.

Camera Direction: Northwest.

Date/Time: April 20, 2022/2:19 P.M.





2: P4200253

Description: The flow from the cleanout flowed to the ditch on the side yard of the residence.

Location: North 82<sup>nd</sup> Street.

Camera Direction: West.

Date/Time: April 20, 2022/2:19 P.M.