


East Palestine Train Derailment - TAGA Route Map - May 11, 2023



For more information, see <https://www.epa.gov/east-palentine-oh-train-derailment>

On May 11, 2023 EPA's Trace Atmospheric Gas Analyzer (TAGA) bus performed air monitoring around the East Palestine Derailment Location, monitoring for n-Butyl Acrylate.

Of the 31,101 real-time readings taken during the day, 100% of the readings were below site-specific mobile thresholds.

 Derailment Location



Prepared For: U.S. EPA Prepared By: U.S. EPA GIS Unit