



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
REGION 5  
77 WEST JACKSON BOULEVARD  
CHICAGO, IL 60604-3590

REPLY TO ATTENTION OF  
ECW-15J

**VIA ELECTRONIC MAIL**

Mayor Curtis McCall Sr.  
City of Cahokia Heights  
103 Main Street  
Cahokia Heights, Illinois 62206  
ymccall@cahokiaillinois.org

Subject: July 6-7, 2023, NPDES SSO Inspection Trip Report for City of Cahokia Heights

Dear Mayor McCall:

Enclosed, please find a copy of the U.S. Environmental Protection Agency Inspection Trip Report that describes and documents the observation made by the EPA inspection team in the City of Cahokia Heights on July 6-7, 2023. The purpose of the reconnaissance inspection in the City of Cahokia Heights was to observe locations where sanitary sewer overflows had happened in the past and document their condition under dry-weather conditions.

If you have any questions or concerns regarding this letter, or the inspection trip report, please contact Dean Maraldo at (312) 353-2098 or at [maraldo.dean@epa.gov](mailto:maraldo.dean@epa.gov).

Sincerely,

RYAN BAHR Digitally signed by RYAN  
BAHR  
Date: 2023.07.12  
14:24:01 -05'00'

Ryan J. Bahr  
Supervisor, Section 2 Water Enforcement and Compliance Assurance Branch

Enclosure

cc: Sharlin Pfeffer, City of Cahokia Heights [spfeffer@cahokiaillinois.org]  
Dennis Traiteur, City of Cahokia Heights [dtraiteur@cahokiaillinois.org]  
Todd Bennett, Illinois EPA [Todd.Bennett@Illinois.gov]  
Joe Stitely, Illinois EPA [Joe.Stitely@Illinois.gov]

**Purpose:** NPDES SSO Inspection Trip Report

**Facility:** Cahokia Heights, Illinois

**NPDES ID Number (No NPDES Permit):** ILN000019

**Date of Inspection:** July 6-7, 2023

**Illinois EPA Inspectors:** None

**EPA Inspectors:**

Dean Maraldo, EPA Region 5; (312) 353-2098; [maraldo.dean@epa.gov](mailto:maraldo.dean@epa.gov)

Joan Rogers, EPA Region 5; (312) 886-2785; [rogers.joan@epa.gov](mailto:rogers.joan@epa.gov)

**City of Cahokia Heights Representatives:** None

**Inspection Trip Report Prepared by:**

Dean Maraldo, EPA Region 5 Inspector

EPA Inspector Signature: DINO MARALDO Digitally signed by DINO MARALDO  
Date: 2023.07.11 09:43:28 -05'00'

**Approver Name & Title:**

Ryan Bahr, Supervisor, Section 2 Water Enforcement and Compliance Assurance Branch

Approval Signature and Date: RYAN BAHR Digitally signed by RYAN BAHR  
Date: 2023.07.12 14:23:32 -05'00'

On July 6-7, 2023, EPA inspectors Dean Maraldo, and Joan Rogers conducted a Sanitary Sewer Overflow (SSO) reconnaissance inspection in the City of Cahokia Heights and observed several lift stations and chronic SSO locations to document whether they were discharging or had evidence of recent discharges. The inspection began at 3:42 P.M. on July 6, 2023, and concluded at 10:30 AM. on July 7, 2023. Prior to the inspection, the last measurable rainfall recorded at the St. Louis Downtown Airport (KCPS) in St. Clair County occurred on July 2 (0.03").

This trip report summarizes the inspection observations. No SSO discharges were observed, and no photographs were taken during the inspection.

On July 6, EPA inspectors observed conditions at several lift stations in the central and eastern portions of Cahokia Heights including lift stations at

**Ex. 7f (Water Infra.)**

No SSO discharges were observed. The inspectors also observed conditions at known SSO locations on streets. Inspectors did not observe SSO discharges and ditches in the area were dry. Inspection activities on July 6 concluded at 4:04PM.

On July 7, EPA inspectors observed conditions at several lift stations in the central portion of Cahokia Heights, including lift stations at

**Ex. 7f (Water Infra.)**

No SSOs were observed. The inspectors also observed conditions at known SSO locations on city streets. Inspectors did not observe SSO discharges and ditches in the area remained dry.

The EPA inspection team concluded the inspection at 10:30 AM. on July 7, 2023.